User Manual

GlacialTech®

Inspiring Cooling Technology
www.GlacialTech.com

•Installation

Step 1

Remove the plastic cover.



Step 2

Place the fasteners at the motherboard's holes.



(Error!)

Step 3

Make sure that all the fasteners are at the original status.



Step 4

Push down on the top of fasteners, you should hear a "click" when pushing down the fastener.



(Error!)

Do not put hands on the top of fan as the pressing point by installation in order to avoid fan hub damage.



Step 5

Connect the fan cable connector to the motherboard CPU fan header.

- FAN APPROVED BY CE & UL
- The specifications are subject to change without notice. All brand names and trademarks are the properties of their respective owners.

For further information, please consult our website: www.GlacialTech.com

© 2010 GlacialTech Inc. All rights reserved.